




# Petromax



## fc1000-sh

**DE** Original-Montageanleitung für  
Spießhalter

**EN** Assembly instructions for  
Skewer Holder

**FR** Instructions de montage pour  
Support à brochettes

**IT** Istruzioni di montaggio per  
Supporto per spiedini

**ES** Instrucciones de montaje para  
Soporte para brochetas

**DA** Monteringsvejledning til  
Spidsholder

**NL** Montagehandleiding voor  
Spiezenhouder

**SV** Monteringsanvisning för  
Spetsställare

**NO** Monteringsanvisning for  
Spydholder




**FI** Kokoamisohje  
Varrasteline

**PL** Instrukcja montażu  
Uchwyt do szaszłyków

**CS** Montážní návod pro  
Držák špízů



RACCOLTA CARTA



|  |                                                           |
|--|-----------------------------------------------------------|
|  | fc1000-sh                                                 |
|  | 21,2 x 3,5 x 3,5 cm<br>8.3 x 1.4 x 1.4 in                 |
|  | 533 g<br>1.2 lbs                                          |
|  | 0 - 350°C<br>32 - 662 °F                                  |
|  | fc1000 • sw-iron • bg-iron<br>wf-iron • sts70 • ls1 • ls2 |



DE Edelstahl • EN Stainless steel  
FR Acier inoxydable • IT Acciaio  
inossidabile • ES Acero inoxidable  
DA Rustfrit stål • NL Roestvrij staal  
SV Rostfritt stål • NO Rustfritt stål  
FI Ruostumaton teräs • PL Stal  
nierdzewna • CS Nerezová ocel